

Series 2000
3G/4G Modem / Router
Firmware Release Notes

Document Number: 0013-001-000632

Document Version: 1.8 (07 July, 2021)

Firmware Version: v1.8.6.0

CYBERTEC

Documentation Control

Generation Date: July 7, 2021

Copyright © 2021 Cybertec Pty Limited

All rights Reserved.

No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, without the prior written permission of Cybertec Pty Limited.

Cybertec Pty Limited has intellectual property rights covering subject matter in this document. Except as expressly provided in any written license agreement from Cybertec Pty Limited, the furnishing of this document does not give you any license to this intellectual property.

Legal Information

The contents of this document are provided “as is”. Except as required by applicable law, no warranties of any kind, either express or implied, including, but not limited to, the implied warranties of merchantability and fitness for a particular purpose, are made in relation to the accuracy and reliability or contents of this document. Cybertec Pty Ltd reserves the right to revise this document or withdraw it at any time without prior notice.

Under no circumstances shall Cybertec Pty Ltd be responsible for any loss of data or income or any special, incidental, and consequential or indirect damages howsoever caused.

More information about Cybertec can be found at the following Internet address: <http://www.cybertec.com.au>

Contents

1	Introduction	1
2	Version	1
3	Applicability	1
4	Version 1.8.6.0 (05/07/2021)	2
4.1	General	2
4.2	New Features	2
4.3	Enhancements	2
4.4	Bug Fixes	3
4.5	Known Issues	3
5	Version 1.8.5.0 (01/04/2021)	4
5.1	General	4
5.2	New Features	4
5.3	Enhancements	4
5.4	Bug Fixes	4
5.5	Known Issues	4
6	Version 1.8.4.0 (29/01/2021)	5
6.1	General	5
6.2	New Features	5
6.3	Enhancements	5
6.4	Bug Fixes	5
6.5	Known Issues	5
7	Version 1.8.3.0 (18/12/2020)	6
7.1	General	6
7.2	New Features	6
7.3	Enhancements	6
7.4	Bug Fixes	6
7.5	Known Issues	6
8	Version 1.8.2.1 (03/12/2020)	7
8.1	General	7
8.2	New Features	7
8.3	Enhancements	7
8.4	Bug Fixes	7
8.5	Known Issues	7

9	Version 1.8.2.0 (13/11/2020)	8
9.1	General	8
9.2	New Features	8
9.3	Enhancements	8
9.4	Bug Fixes	9
9.5	Known Issues	9
10	Version 1.8.1.0 (11/05/2020)	10
10.1	General	10
10.2	New Features	10
10.3	Enhancements	10
10.4	Bug Fixes	11
10.5	Known Issues	11
11	Version 1.8.0.1 (19/12/2019)	12
11.1	General	12
11.2	New Features	12
11.3	Enhancements	12
11.4	Bug Fixes	12
11.5	Known Issues	12
12	Version 1.8.0.0 (15/11/2019)	13
12.1	General	13
12.2	New Features	13
12.3	Enhancements	13
12.4	Bug Fixes	14
12.5	Known Issues	14
13	Firmware Upgrade Procedure	15
13.1	Connect to the Web interface	15
13.2	System Backup and Upgrade	16

1 Introduction

This document provides a summary of the firmware changes and details the firmware upgrade procedure for the Cybertec Series 2000 of 3G and 4G Modem / Routers.

2 Version

The latest version of the Series 2000 firmware is v1.8.6.0.

The firmware files for the current release are:

- **Series 2000 Model 2155/2155X & Model 2255/2255X** : S2155-v1.8.6.0.zip
- **Series 2000 Model 2455/2455X** : S2455-v1.8.6.0.zip
- **Model DMM-250 & Model DMM-450** : XMM250-v1.8.6.0.zip

The zip file contains two files, the upgrade file, for example S2155-v1.8.6.0.upg and the MD5 hash of the upgrade file. The upgrade file is the file to be used to upgrade the unit.

3 Applicability

The firmware described in this document is applicable for the following models:

- Series 2000
 - Model 2155 / 2155X
 - Model 2255 / 2255X
 - Model 2455 / 2455X
- DMM-250
- DMM-450

The firmware upgrade will fail for any model not listed above.

4 Version 1.8.6.0 (05/07/2021)

4.1 General

- This is an enhancement and bug fix release.

4.2 New Features

- Alternative route feature added.

4.3 Enhancements

- IPsec:
 - ikev2 added.
 - Multiple tunnel mapping initialisation improvements.
- Roaming improvements:
 - General scan improvements.
 - Deny list name changed to Ignore list.
 - Added in Preferred PLMN roaming mode.
 - Ability to upload a CSV file of the preferred PLMN list.
 - Strict mode added - scan must match the configured criteria otherwise no connection will be made at all.
 - Roaming mode and lists configurable for SIM 1 and Sim 2 (if available).
- DHCP client improvements:
 - Option to add DNS obtained to DNS list.
 - Option to use obtained gateway as primary default gateway.
- CLI improvements:
 - Config reset command updated to require password and automatically reboot.
 - Upgrade command now has options for username and password.
- Web improvements:
 - Automatically move cursor to username text field on login page.
 - Added ability to configuration reset the unit.
 - Return correct line power state on 5455 Rev2.
 - Band 40 added to custom band selection on DMM450 model.
- Logging improvements.
- Connection maintenance improvements.
- Startup improvements for the 2155X/2255X models.
- Stability improvements.

4.4 Bug Fixes

- Roaming improvements:
 - Fix bugs with scan not completing properly.
 - Fix bug with Rev2 models showing UMTS bands in scan when in LTE Only mode.
 - Ignore list (previously deny list) now saves correctly.
- Serial ports:
 - Fix inversion of CTS / RTS signal when offline.
 - Fixed CTS signal read and web page indicator.
 - Correctly handle signal naming of DCE and DTE ports.
- Web improvements:
 - Web certificate generation issue resolved.
 - Hostname fails with all special characters besides a hyphen. Previous behaviour was to silently fail and full stop and underscore characters were accepted.
- LLDP issue resolved..
- Ethernet MTU issue resolved.
- Fixed ability to specify IP address for PPPOA on 5455 Rev2.

4.5 Known Issues

- No known issues.

5 Version 1.8.5.0 (01/04/2021)

5.1 General

- This is an enhancement and bug fix release.

5.2 New Features

- No new features.

5.3 Enhancements

- Upgrader improvements.
- Max password length increased to 128 characters.
- Wireless MTU configuration support and display.
- DSL “Timeout for network initialisation” setting default changed from 120s to 600s.
- Model 5455 Rev2 ADSL improvements.
- SMS added support for 8 bit and 16 bit modes.

5.4 Bug Fixes

- IPsec fix for packet re-establishments after wireless disconnections.
- DynDNS enable not persistent issue resolved.
- netstat CLI fix.
- SMS resolved buffering issue in modem emulation mode.
- Unsupported hardware failing into CSD mode, due to imported configuration resolved.
- Model 5455 rebooting on 0 failed attempts resolved.

5.5 Known Issues

- No known issues.

6 Version 1.8.4.0 (29/01/2021)

6.1 General

- This is an enhancement and bug fix release.

6.2 New Features

- No new features.

6.3 Enhancements

- Security improvements.
- DNS update.
- OpenVPN: TLS improvements
- Added support for routing between LAN ports, when in split port mode.

6.4 Bug Fixes

- DHCP: resolved issue of custom DNS on LAN2.
- Model 2455X Rev 1 -Wireless Interface:
 - Resolved issue where DNS server provided by the network may not be correctly applied.
 - Resolve issue of no packet traffic over interface.

6.5 Known Issues

- No known issues.

7 Version 1.8.3.0 (18/12/2020)

7.1 General

- This is an enhancement and bug fix release.

7.2 New Features

- No new features.

7.3 Enhancements

- Added in ability to specify the IPSec CA DN required.
- Added 0.3.38 (GSM7) terminal setting for SMS in Modem Emulation Mode.
- Ethernet / LAN
 - Enhanced how MTU is configured.
- Updated and improved SNMP.

7.4 Bug Fixes

- DHCP: Fixed issue with importing DHCP configuration settings from previous firmware revisions.
- Web: Fixed issue with routing table not rendering correctly.
- Wireless Interface: Removed the SetMNB application for non-MNO configured units.
 - This caused an issue with connections on some carriers when using private APNs.

7.5 Known Issues

- No known issues.

8 Version 1.8.2.1 (03/12/2020)

8.1 General

- This is an enhancement release.
- First version to fully support Model 5455 Rev2.

8.2 New Features

- No new features

8.3 Enhancements

- Added support for Model 5455 Rev2.

8.4 Bug Fixes

- No bug fixes

8.5 Known Issues

- No known issues.

9 Version 1.8.2.0 (13/11/2020)

9.1 General

- This is an enhancement and bug fix release.

9.2 New Features

- DHCP client functionality on LAN ports.

9.3 Enhancements

- Added support for Model 5450 and Model 5455.
- Added support for Model 5455 Rev2.
- Ethernet / LAN
 - Improved split port support.
 - Bridge mode works correctly with PPPoE.
 - Individual LAN port control and monitoring.
 - If a gateway is set on LAN, default/static routes can be specified.
 - MAC filtering added on LAN2.
 - ARPs response mode can be set.
 - The mode are:
 - Strict - Reply only if the target IP address is a local address configured on the incoming interface and both with the sender's IP address are part of the same subnet on this interface.
 - Normal - Reply only if the target IP address is a local address configured on the incoming interface.
 - Permissive - Reply for any local target IP address, configured on any interface.
- DHCP
 - Added client functionality to LAN ports.
 - Added server functionality to LAN2.
 - Added ability to specify NTP and DNS settings on DHCP server.
- Dynamic DNS
 - Added ability to specify refresh period.
- Web:
 - Add routes pages
 - Time and date now displayed on all pages.
- Wireless:
 - General stability improvements.
 - Improved LTE connections for 2155X / 2255X
 - Improvements to Private APN authentication and connection establishment.
 - Improved roaming support. Details as follows:
 - On boot a scan is performed to determine which networks are available.
 - All available networks are scanned.
 - Any network in the "Denied Networks" list will not be included in the scan.
 - Depending on the Roaming Mode a network connection will be attempted.

- If successful, remain on the selected network.
- If connection maintenance (remote ping) is enabled:
 - On failure the network is added to a temporary Deny List.
 - This is a standard ping test, not a performance test.
- If the all available networks are on the temporary deny list:
 - The temporary deny list will be cleared.
 - A network scan will be performed.
 - Attempt to connect to a network based on Roaming Mode setting.
 - This prevents all available networks being locked out should the ping server not respond.
 - Adding a network to the Deny List will have immediate effect.
 - If the network is currently connected it will be disconnected.

9.4 Bug Fixes

- IPsec: Resolved Back to Back ping issue.
- VRRP:
 - Resolved issue of not going to backup when Ethernet interface is disabled.
 - Resolved issue on 5455 not going to backup when xDSL cable is removed.
- Bridged PPPoE: Resolved packet loss issue.
 - For this to work there are restrictions:
 - The Ethernet port configuration must be in split mode; and
 - Bridge mode can only be set to LAN1.
- Resolved the MAC address filtering stability issue.
- Resolved alias IP issue on DMM units.
- Resolved root and subordinate certificate issue.

9.5 Known Issues

- No known issues.

10 Version 1.8.1.0 (11/05/2020)

10.1 General

- This is an enhancement and bug fix release.

10.2 New Features

- DMM-450 & DMM-250: Added remote syslog support.

10.3 Enhancements

- Added SHA2 support to:
 - IPsec
 - Open VPN
 - Web server
 - SNMP
 - SCEP
- IPsec:
 - Added XAuth server
 - Added ability to enforce strict settings.
- Security:
 - General improvements.
 - Password cannot be set to the default.
 - Warning if password has not been changed from default.
 - TLS upgrade.
- Web:
 - Improved Javascript error handling on various web pages.
 - Added hardware version to information page.
- Wireless:
 - Improved LTE connection establishment.
 - Improved LTE authentication prior to network connection. This reduces instances of connection to UMTS prior to connection to LTE.
 - Improved LTE connection times in some situations.
 - Improvement to band swapping on some models.
 - Improved roaming support.
 - Improvements to Private APN authentication and connection establishment.
- Serial Server: DNP3 primary / backup support improved.
- Log: Improvements to log rotation.
- VRRP: Added ability to add polling source address.
- SCEP: added support for non chained certificates.
- PPP: Updated.

10.4 Bug Fixes

- IPsec: Individual tunnel restart no longer causes all tunnels to restart.
- Custom route: Fixed issue where custom routes were not maintained through upgrade.
- CLI: Fixed issue with firmware upgrade command.
- SMS: Fixed case sensitivity issue for VPN tunnel trigger.
- Firewall: Fixed issue with limit on number of rules. Limit is now 150.

10.5 Known Issues

- No known issues.

11 Version 1.8.0.1 (19/12/2019)

11.1 General

- This is an enhancement and bug fix release.
- When upgrading from firmware version V1.8.0.0 NAPT settings should be checked.

11.2 New Features

- No New features

11.3 Enhancements

- Improved upgrader.
- Improvements to web pages.
- Improvements to CLI.

11.4 Bug Fixes

- Fixed issue with 3G connection on some 3G only models.
- Fixed RADIUS server authentication.
- Fixed issue with OpenVPN dropping route on configuration update.
- Fixed interface issue when NAPT disabled.

11.5 Known Issues

- No known issues.

12 Version 1.8.0.0 (15/11/2019)

12.1 General

- This is an enhancement and bug fix release.

12.2 New Features

- Web: Improve the web authentication process.
- Web: All web interactions are now Session based.
- Web: Added logout capabilities.
- LLDP: Added support for LLDP
- LLDP: Disable flooding of LLDP packets by default (can be re-enabled).
- mDNS: Added basic mDNS capabilities.
- LAN: A Link Local address can be enabled on the LAN interface (and discovered through mDNS)
- LAN: Allow ethernet ports to be separated into two independent networks.
- DMM-450: Added Loopback Interface configuration.
- DMM-450: Added support for MAC filtering.

12.3 Enhancements

- Web: Improved Javascript and functionality of various web pages.
- DMM-450: Raised the number of certificates from 1 to 4.
- DMM-450: Increase the number of IPSec tunnels from 1 to 3.
- IPSEC: Allow the specification of the Source Address various connections.
- Interface: Allow strict ARP checking to be enabled on Ethernet ports (default off).
- DHCP: Move configuration to DHCP specific web page.
- DNS: Move “Automatically obtain DNS from WAN interface” to the dns page.
- MSP: Better reporting of Signal Quality information for Rev2 Units.
- MSP: Improve the roaming code to support more networks and moving between technologies better.
- Wireless: Add additional LTE band Connectivity on some units.
- Wireless: Add option to enable or disable case sensitivity for SMS triggers.
- SNMP: Added Configurable Sysname.
- SNMP: Add button to send a “test” trap to all trap destinations. This is a temperature trap with a 237C value.
- SNMP: Added the device MAC address to the unit’s MIB (Cybertec OID enterprise.15428.1.5.1.4).
- General: Shutdown improvements.
- General: Enable the LinkLocal Interface and MDNS on the initial boot (until a configuration has been saved).
- General: Improve the routing efficiently through better interrupt management.

12.4 Bug Fixes

- Loopback: Correctly set address when changed while enabled.
- SerialServer: Fixed an issue with Reverse Telnet.
- SerialServer: Fixed issues with disconnection and reconnection of dnp3, modem emulation and tcp serial modes.
- HW: Fixed an issue with frequency band display on Model 2455X Rev2 Hardware.
- GPS: Correctly save and restore the authentication required config.
- DynDNS: Fix an issue where the password was not being correctly restored after reboot.
- Time: If a date has not be saved previously default to the BuildDate rather than Epoch.
- SMS: Remove triggers that are not valid for that unit (EG CSD on a unit without CSD capabilities).
- SNMP: Block SNMP traffic until the SNMP agent has time to correctly initialise.
- SNMP: Do not Populate SysContact or SysLocation if empty.
- Interface: Update packet counters periodically to remove “Large Jump” errors.
- CLI: Fixed an issue displaying SMS support.
- Diagnostics: Clear Ping trace on Config Reset.
- OpenVPN: Display the import OpenVPN configuration.

12.5 Known Issues

- No known issues.

13 Firmware Upgrade Procedure

The firmware upgrade procedure for the Series 2000 3G/4G Modem / Router is described. The same procedure can be used for all models in the product range.

13.1 Connect to the Web interface

- Connect to the Web interface of the modem either via the Ethernet interface or the wireless interface if web access is enabled.
- If connecting via the Ethernet interface:
 - Connect an Ethernet cable between the modem and the PC which will be used for the upgrade.
 - Open a web browser on the PC and enter the IP address of the LAN address of the modem. Note: The IP address of the modem may be configured differently for each installation. The default IP address is 10.10.10.10
- If connecting via the wireless interface:
 - Open a web browser on the PC and enter the IP address of the wireless interface.
- When prompted supply the user-name and password.
- The main status page should now be displayed.
- If the main page is not shown check:
 - If using the Ethernet interface:
 - The Ethernet cable is connected correctly to the modem and the PC.
 - The IP address of the modem is correct.
 - The Ethernet ports are enabled.
 - If using the wireless interface:
 - The wireless IP address is correct and is publicly accessible.
 - The firewall rules have been set to allow wireless web access.

13.2 System Backup and Upgrade

- Select System ▸ Backup & Upgrade. The System Backup & Upgrade page will be displayed as shown in Figure 1.




Figure 1: The System Backup & Upgrade page.

13.2.1 Backup Configuration

- It is recommended to save the current configuration file.
- The configuration of the modem is forward compatible. This means the configuration of the modem will still be correct after a firmware upgrade to a later version even though the format used to store the configuration may be changed.
- The configuration of the modem is not always backward compatible. This means that if the modem firmware is replaced with an earlier version the configuration file may not be readable by the earlier version of firmware and so the configuration will revert to the default settings. If the configuration file from the earlier version was saved prior to the upgrade then this configuration can be loaded into the modem to restore the previous settings after reverting to the earlier revision of firmware.
- To save the configuration click the link in the section titled “Backup current configuration” as shown in Figure 2 and save the file to the local machine.



Figure 2: System configuration backup.

- To restore a configuration click the Browse button in the section title “Restore a saved configuration” as shown in Figure 3 then click the Upload button.

Restore a saved configuration	
Select configuration file	<input type="text"/> Browse...
Upload	

Figure 3: System configuration restore.

13.2.2 Firmware Upgrade

- In the section titled “Upgrade Series 2000 firmware” click the Browse button and navigate to and select the upgrade file appropriate for the modem being upgraded as shown in Figure 4. Refer to Section 2 on page 1 for the firmware file name and version number details.
- If the incorrect file is selected the upload will fail and report an error.

Upgrade Series 2000 firmware	
Current firmware version	1.21
Select upload file	<input type="text" value="00-images/S2000-v140.upg"/> Browse...
Upload	

Figure 4: Select the upgrade file.

- Click the Upload button. The file will now be transferred to the modem.
- When the upload is complete the Upgrade section of the page will change to be similar to that shown in Figure 5.

Upgrade Series 2000 firmware	
Status of uploaded file	Passed
Filename	series-2000-v140.img
Release	1.40
Build date	24/04/2010
Upgrade	Cancel Upgrade

Figure 5: File has been uploaded to the modem.

- Check that the information shown is correct.
- If the data is correct click the “Upgrade” button.



Once the Upgrade has started power must be maintained to the modem to prevent corruption of the Flash memory.

- The Upgrade section of the page will now show a message as shown in Figure 6.




Figure 6: The Upgrade page.

- During the upgrade:
 - the top two front panel LEDs will flash alternatively Red then Green.
 - the modem will disconnect from the wireless network.
 - the modem will not respond to any network traffic.
 - the modem will re-boot when the upgrade has completed
- When the Upgrade has completed and the modem has re-booted the new firmware version can be checked in the System Information page. Figure 7 is an example of the System Information page after the upgrade has completed. Note only the Application Version is shown.



Figure 7: The System Information page after the upgrade.

CYBERTEC

Cybertec Pty Limited
ABN 72 062 978 474
19 Buffalo Road
Gladesville NSW 2111 Australia
Phone: +61 2 9807 5911
www.cybertec.com.au